

[\(close window\)](#)

Motosport Hillsboro - Honda Suzuki Kawasaki

KTM

809 NE 28th Avenue

Hillsboro, OR 97124

(503) 648-4555

www.hillsboromotorcycles.com

2005 SUZUKI
VL1500, C90,T 2005-
2006
FUEL INLET

July 12, 2007





FIG.38

VL1500K5 E03 E28_038
FUEL INLET

REF#	PART	#REQ	REMARKS	YOUR PRICE
1	INLET, FUEL TANK 44190-10F00	1		\$87.24
2	MOLDING 68241-04X50-00B	1		\$14.93
3	CUSHION	1		\$2.07

	11179-45D00		
4	TRAY, FUEL INLET 44261-10F00	1	\$11.57
5	HOSE, WATER DRAIN (L:2000->670 09352-70103-00B	1	\$10.98
6	JOINT, FUEL HOSE 09367-08001	1	\$1.81
7	CLAMP (L:165) 09407-18402	1	\$1.11
8	.SCREW, OUTER 02142-0516A	3	\$0.74
9	WASHER 09160-05046	3	\$0.93
10	SPACER, VACUUM SW VALVE 09180-05047	3	\$1.08
11	CUSHION 44559-10F00	3	\$2.29
12	VALVE, FUEL INLET 89280-50F00	1	\$8.17
13	CAP ASSY, FUEL TANK 44200-10F01	1	\$37.53
14	HOSE, INLET 44422-10F00	1	\$26.06
15	CLAMP 09400-52312	2	\$1.89

[\(close window\)](#)

**Motosport Hillsboro - Honda Suzuki Kawasaki
KTM**

**809 NE 28th Avenue
Hillsboro, OR 97124
(503) 648-4555**

www.hillsboromotorcycles.com

**2005 SUZUKI
VL1500, C90,T 2005-
2006**

July 12, 2007

(prices subject to change without notice)

