

[\(close window\)](#)

**Motosport Hillsboro - Honda Suzuki Kawasaki**

**KTM**

**809 NE 28th Avenue**

**Hillsboro, OR 97124**


**(503) 648-4555**


[www.hillsboromotorcycles.com](http://www.hillsboromotorcycles.com)

**2005 SUZUKI  
VL1500, C90,T 2005-  
2006**

**FOOTREST**

July 12, 2007



**FIG.36**

VL1500K5 E03 E28\_036  
FOOTREST

| REF# | PART                                   | #REQ | REMARKS | YOUR PRICE |
|------|--|------|---------|------------|
| 1    | FOOTREST ASSY, FRONT RH<br>43501-10F10 | 1    |         | \$126.78   |
| 2    | FOOTREST ASSY, FRONT LH<br>43502-10F10 | 1    |         | \$126.78   |
| 3    | .RUBBER                                | 2    |         | \$38.73    |

|    |   |   |         |
|----|---|---|---------|
|    | 43550-10F10                                 |   |         |
| 4  | BOLT, BANK SENSOR<br>43576-07D01            | 2 | \$4.81  |
| 5  | BOLT<br>01550-0610A                         | 6 | \$1.04  |
| 6  | WASHER<br>09160-06503                       | 6 | \$0.91  |
| 7  | .CUSHION<br>09320-10016                     | 6 | \$1.31  |
| 8  | BRACKET, FRONT FOOTREST RH<br>43510-10F00   | 1 | \$97.32 |
| 9  | BRACKET, FRONT FOOTREST LH<br>43520-10F00   | 1 | \$97.32 |
| 9A | .CUSHION<br>61544-94500                     | 2 | \$0.88  |
| 10 | BOLT<br>01580-10353                         | 4 | \$1.89  |
| 11 | PIN<br>43539-10F00                          | 2 | \$4.22  |
| 12 | SPRING, PEDAL RETURN<br>09443-11033         | 2 | \$2.29  |
| 13 | E RING, PINION<br>08332-1106A               | 2 | \$0.74  |
| 14 | FOOTREST ASSY, PILLION RH<br>43600-38E00    | 1 | \$39.53 |
| 15 | FOOTREST ASSY, PILLION LH<br>43700-38E00    | 1 | \$39.53 |
| 16 | .RUBBER, PILLION FOOTREST<br>43612-38A00    | 2 | \$5.62  |
| 17 | .PLATE, RUBBER STOPPER<br>43632-38A00       | 2 | \$3.14  |
| 18 | .SCREW<br>09127-05017                       | 4 | \$1.15  |
| 19 | BRACKET, PILLION FOOTREST RH<br>43811-10F10 | 1 | \$59.87 |
| 20 | BRACKET, PILLION FOOTREST LH<br>43821-10F10 | 1 | \$59.87 |
| 21 | BOLT, EXHAUST PIPE<br>09106-08165           | 4 | \$2.18  |
| 22 | PIN<br>09208-08010                          | 2 | \$1.41  |
| 23 | .SPRING<br>09440-05005                      | 2 | \$0.67  |
| 24 | BALL, DETENT NO.1<br>06111-07004            | 2 | \$0.67  |
| 25 | PLATE, RH<br>43816-10F00                    | 1 | \$2.78  |
| 26 | PLATE, LH<br>43826-10F00                    | 1 | \$2.78  |
| 27 | E RING, PINION<br>08332-1106A               | 2 | \$0.74  |

[\(close window\)](#)

## Motosport Hillsboro - Honda Suzuki Kawasaki KTM


809 NE 28th Avenue  
Hillsboro, OR 97124  
(503) 648-4555

[www.hillsboromotorcycles.com](http://www.hillsboromotorcycles.com)

**2005 SUZUKI  
VL1500, C90,T 2005-  
2006**

July 12, 2007

(prices subject to change without notice)



print