

[\(close window\)](#)

Motosport Hillsboro - Honda Suzuki Kawasaki

KTM

809 NE 28th Avenue

Hillsboro, OR 97124

(503) 648-4555

www.hillsboromotorcycles.com

**2005 SUZUKI
VL1500, C90,T 2005-
2006
STARTER CLUTCH**

July 12, 2007





FIG.8

VL1500K5 E03 E28_008
STARTER CLUTCH

REF#	PART	#REQ	REMARKS	YOUR PRICE
1	GEAR, STARTER IDLE NO.1 12611-10F00	1		\$31.97
2	PIN 09206-11015	1		\$4.92
3	CLUTCH SET, STARTER	1		\$187.60

	12600-10860		
4	.PLUG, OIL GALLERY 07130-08163	6	\$1.44
5	LIMITER ASSY, STARTER IDLE 12600-24B00	1	\$113.21
6	BUSH 12618-31D01	2	\$12.38
7	WASHER, CL RLSE 09181-10195	2	\$1.04

[\(close window\)](#)**Motosport Hillsboro - Honda Suzuki Kawasaki****KTM****809 NE 28th Avenue****Hillsboro, OR 97124****(503) 648-4555**www.hillsboromotorcycles.com**2005 SUZUKI
VL1500, C90,T 2005-
2006**

July 12, 2007

(prices subject to change without notice)

