

[\(close window\)](#)

**Motosport Hillsboro - Honda Suzuki Kawasaki**

**KTM**

**809 NE 28th Avenue**


**Hillsboro, OR 97124**

**(503) 648-4555**

[www.hillsboromotorcycles.com](http://www.hillsboromotorcycles.com)

**2005 SUZUKI  
VL1500, C90,T 2005-2006  
REAR MASTER  
CYLINDER**

July 12, 2007



This exploded view diagram illustrates the assembly of a front wheel hub. The components are numbered as follows:

- 1:** Hub assembly
- 2:** Hub nut
- 3:** Hub cap
- 4:** Hub seal
- 5:** Hub nut washer
- 6:** Hub nut lock
- 7:** Hub nut lock washer
- 8:** Hub nut lock cap
- 9:** Hub nut lock cap screw
- 10:** Hub nut lock cap screw
- 11:** Hub nut lock cap screw
- 12:** Hub nut lock cap screw
- 13:** Hub nut lock cap screw
- 14:** Hub nut lock cap screw
- 15:** Hub nut lock cap screw
- 16:** Hub nut lock cap screw
- 17:** Hub nut lock cap screw
- 18:** Hub nut lock cap screw
- 19:** Hub nut lock cap screw
- 20:** Hub nut lock cap screw
- 21:** Hub nut lock cap screw
- 22:** Hub nut lock cap screw
- 23:** Hub nut lock cap screw
- 24:** Hub nut lock cap screw
- 25:** Hub nut lock cap screw
- 26:** Hub nut lock cap screw
- 27:** Hub nut lock cap screw
- 28:** Hub nut lock cap screw
- 29:** Hub nut lock cap screw
- 30:** Hub nut lock cap screw
- 31:** Hub nut lock cap screw

A 'FWD' arrow at the bottom right indicates the front of the vehicle.

REF#	PART	#REQ	REMARKS	YOUR PRICE
1	CYLINDER ASSY, REAR MASTER 69600-10F00	1		\$132.20
2	.PISTON / CAP SET 69600-04820	1		\$16.94
3	..BOOT	1		\$2.89

4	69691-00A00 .ROD, PUSH 69670-00B21	1	\$12.53
5	.NUT 69693-05A00	2	\$0.85
6	.YOKE 69692-27A30	1	\$7.25
7	.O RING 69686-34200	1	\$1.59
8	.CONNECTOR 69672-05A00	1	\$3.03
9	.SCREW 02112-7412A	1	\$1.08
10	SCREW, REGULATOR 07120-06163	2	\$1.08
11	TANK ASSY, RESERVOIR 69740-10F00	1	\$45.55
12	.DIAPHRAGM 59667-49460	1	\$5.33
13	.PLATE, DIAPHRAGM 59668-41C00	1	\$5.10
14	.CAP 59669-41C00	1	\$17.11
15	.SCREW 69689-49300	2	\$0.85
16	BOLT 01550-0616A	1	\$1.04
17	HOSE, RESERVOIR TANK 69731-10F00	1	\$6.91
18	CLIP 09401-13417	2	\$1.15
19	COVER, RESERVOIR TANK 69795-10F00	1	\$8.43
20	BOLT 01550-0610A	1	\$1.04
21	WASHER 08322-0106A	1	\$0.93
22	.SHAFT, SHALLOW DRIVE ARM 09200-06068	1	\$2.12
23	WASHER 08322-0106A	1	\$0.93
24	COTTER PIN 04111-20158	1	\$0.67
25	HOSE, REAR BRAKE 69480-10F20	1	\$77.91
26	WASHER (10X15X1.5) 09161-10009	4	\$0.93
27	BOLT (10X1.25X22) 09360-10042	2	\$3.37
28	CLAMP, BRAKE HOSE 69268-10F10	1	\$5.03
29	CLAMP, BRAKE HOSE 59268-01D10	1	\$3.96
30	BOLT 02162-0612A	1	\$0.85
31	BOLT 01550-0616A	1	\$1.04

[\(close window\)](#)

## Motosport Hillsboro - Honda Suzuki Kawasaki

**KTM**

**809 NE 28th Avenue**

**Hillsboro, OR 97124**


**(503) 648-4555**

[www.hillsboromotorcycles.com](http://www.hillsboromotorcycles.com)

**2005 SUZUKI  
VL1500, C90,T 2005-  
2006**

July 12, 2007

(prices subject to change without notice)



print